Blue Hill Trail and South St Route

Bicycle/Pedestrian Hazards

These observations were made during an assessment of this route on June 2, 2017.

This route begins and ends at the small parking area at the trailhead on Parker Point Rd.

This route was ultimately not selected for mapping and promotion.

A. There are no sidewalks or painted shoulder lanes on Parker Point Rd.
B. On-street parking on Parker Point Rd. blocks pedestrian access to the sidewalk on Main St.
C. The sidewalk on Main St./Tenney Hill is narrow and poles act as barriers in the pedestrian path.
D. The crosswalk across South St. adjacent to the rotary needs to be repainted.
E. The sidewalk abruptly ends on South St. with no crosswalk. There is no designated pedestrian access to the Blue Hill Heritage Trust trailhead off South St.
F. The Blue Hill Heritage Trust trail is a wilderness trail, requiring significant agility and motility. It is not appropriate for pedestrians of all abilities.

Pedestrian Hazards



A. There are no sidewalks or painted shoulder lanes on Parker Point Rd., and in some areas pavement is broken and/or uneven.

B. On-street parking on Parker Point Rd. blocks pedestrian access to the sidewalk on Main St.



C. The sidewalk on Main St./Tenney Hill is narrow, in poor repair, and poles act as barriers in the pedestrian path.

D. The crosswalk across South St. adjacent to the rotary needs to be repainted.



E. The sidewalk abruptly ends on South St. with no crosswalk. There is no designated pedestrian access to the Blue Hill Heritage Trust trailhead off South St.

F. The Blue Hill Heritage Trust trail is a wilderness trail, requiring significant agility and motility. It is not appropriate for pedestrians of all abilities.