Castine Leg Workout Route

Bicycle/Pedestrian Hazards

These observations were made during an assessment of this route on June 2, 2017.

This route begins and ends on Main St.

A. The Sea St. sidewalk beyond Green St. is narrow and crowded by vegetation.
B. There is no designated pedestrian way along Sea St. between Main St. and Pleasant St.
C. There is no sidewalk or painted shoulder on Perkins St. between Pleasant St. and Dressers Ln.
D. The Perkins St. sidewalk between Dressers Ln and Tarratine St. is in poor condition.
E. There is no crosswalk at the intersection of Perkins St. and Tarratine St., and broken pavement in this area creates a pedestrian hazard.
F. There is no sidewalk or painted shoulder on Tarratine St.
G. There is no sidewalk or painted shoulder on Battle Ave. between Tarratine St. and Main St.
H. There is no crosswalk at the intersection of Battle Ave. and Main St.

Pedestrian Hazards

A. The Water St. sidewalk beyond Green St. is narrow and crowded by vegetation.

B. There is no designated pedestrian way along Sea St. between Main St. and Pleasant St.

C. There is no sidewalk or painted shoulder on Perkins St. between Pleasant St. and Dressers Ln.

D. The Perkins St. sidewalk between Dressers Ln. and Tarratine St. is in poor condition.



E. There is no crosswalk at the intersection of Perkins St. and Tarratine St., and broken pavement in this area creates a pedestrian hazard.

F. There is no sidewalk or painted shoulder on Tarratine St., and potions of the shoulder have broken and/or uneven pavement.



G. There is no sidewalk or painted shoulder on Battle Ave. between Tarratine St. and Main St.



H. There is no crosswalk at the intersection of Battle Ave. and Main St.