Castine Water View Route

Bicycle/Pedestrian Hazards

These observations were made during an assessment of this route on June 2, 2017.

This route begins and ends at the corner of Court St. and Pleasant St.

A. The sidewalk on Court St. between Green St. and Dyer Ln. is narrow and in poor repair.
B. There is no sidewalk or painted shoulder on Court St. beyond Dyer Ln.
C. There is no sidewalk or painted shoulder on Spring St.
D. There is no sidewalk or painted shoulder on Water St. between Spring St. and Green St.
E. The Sea St. sidewalk beyond Green St. is narrow and crowded by vegetation.
F. There is no designated pedestrian way along Sea St. between Main St. and Pleasant St.
G. The sidewalk on Pleasant St. between Perkins St. and Court St. is in poor repair.

Pedestrian Hazards

A. The sidewalk on Court St. between Green St. and Dyer Ln. is narrow and in poor repair.



B. There is no sidewalk or painted shoulder on Court St. beyond Dyer Ln.

C. There is no sidewalk or painted shoulder on Spring St.

D. There is no sidewalk or painted shoulder on Water St. between Spring St. and Green St.

E. The Water St. sidewalk beyond Green St. is narrow and crowded by vegetation.

F. There is no designated pedestrian way along Sea St. between Main St. and Pleasant St.

G. The sidewalk on Pleasant St. between Perkins St. and Court St. is in poor repair.