Franklin

Bicycle/Pedestrian Hazards

These observations were made during an assessment on May 30, 2017.

No on-road routes were ultimately selected for mapping and promotion in Franklin.

A. Photo taken on Route 200, just north of the intersection of Route 182. Narrow, unpaved road shoulders inhibit safe bicycle and pedestrian usage.
B. Photos taken on Route 182 in Franklin. Narrow, unpaved road shoulders paired with heavy through-traffic inhibit safe bicycle and pedestrian usage.

Pedestrian Hazards

A. Photo taken on Route 200, just north of the intersection of Route 182. Narrow, unpaved road shoulders inhibit safe bicycle and pedestrian usage.

B. Photos taken on Route 182 in Franklin. Narrow road shoulders, broken pavement, and sediment accumulation paired with heavy through-traffic inhibit safe bicycle and pedestrian usage.