Winter Harbor Village Route

Bicycle/Pedestrian Hazards

These observations were made during an assessment of this route on May 30, 2017.

This route begins and ends by the Town office on School St.

A. There is loose sediment in several areas of the sidewalk and road shoulder along Main St.
B. The Newman St. sidewalk between Main St. and Navy Dr. switches sides several times, and crosswalks are inconsistent.
C. Navy Dr. does not have sidewalks.
D. There is no crosswalk at the intersection of Navy Dr. and Newman St.

Pedestrian Hazards



A. There is loose sediment that collects on the sidewalk and road shoulder along Main St., which can cause traction hazards for pedestrians, bicyclists, and wheelchair-bound users.

B. The Newman St. sidewalk between Main St. and Navy Dr. switches sides several times.



C. Navy Dr. does not have sidewalks.

D. There is no crosswalk at the intersection of Navy Dr. and Newman St.